UNOFFICIAL COPY

PREPARED BY:

Name:

Shell Oil Products US

Attention: John Robbins

2401637267

Doc#: 0401632082

Eugene "Gene" Moore Fee: \$38.50 Cook County Recorder of Deeds Date: 01/16/2004 12:22 PM Pg: 1 of 8

Address:

603 Diehl Road, Suite 103

Naperville, Illinois 60563

RETURN TO

Name:

Sheil Oil Products US

Attention: John Robbins

Address:

603 Diehl Road, Suite 103

Naperville, Illinois ou 563

(TFE ABOVE SPACE FOR RECORDER'S OFFICE)

LEAKING UNDERGROUND STORAGE TANK ENVIRONMENTAL NOTICE

THE OWNER AND/OR OPERATOR OF THE LEAKING UNDLEGROUND STORAGE TANK SYSTEM(S) ASSOCIATED WITH THE RELEASE REFERENCED BELOW, V 17 HIN 45 DAYS OF RECEIVING THE NO FURTHER REMEDIATION LETTER CONTAINING THIS NOTICE, MUST SUBMIT THIS NOTICE AND THE REMAINDER OF THE NO FURTHER REMEDIATION LETTER 75 THE OFFICE OF THE RECORDER OR REGISTRAR OF TITLES OF COOK COUNTY IN WHICH THE SITE DESCRIBED BELOW IS LOCATED.

Illinois EPA Number: 0312315038

LUST Incident No.: 942158

Shell Oil Products US, the owner and/or operator of the leaking underground storage tank system(s) associated with the above-referenced incident, whose address is 603 Diehl Poad, Suite 103, Naperville, Illinois, has performed investigative and/or remedial activities for the site identified as follows and depicted on the attached Site Base Map:

- 1. Legal Description or Reference to a Plat Showing the Boundaries: See Attachment
- 2. Common Address: 14301 South Wolf Road, Orland Park, Illinois
- 3. Real Estate Tax Index/Parcel Index Number: 27-08-100-056-0000
- 4. Site Owner: Shell Oil Products US
- 5. Land Use Limitation: There are no land use limitations.
- 6. See the attached No Further Remediation Letter for other terms.

jrm


Leaking Underground Storage Tank Environmental Notice

0401632082 Page: 2 of 8 104 (11) 9/20/94 121/94 40.002 40.002 0.004 **WOLF ROAD** B <0.002 T <0.002 E <0.002 × <0.002 GP8.4 (4) 1/23/98 B <0.002 T <0.002 E <0.002 X <0.002 GP8-4 (10') 1/23/98 S-101 (13) B 0.003 T <0.002 E <0.002 X <0.002 9/20/94 S-105 (11) 9/21/94 40.002 0.004 0.003 DRAINAGE DITCH S-102 (11) 9/20/94 B 0.002 T <0.002 E <0.002 X <0.002 S-106 (11') 9/21/94 GRASS \$0.002 \$0.002 \$0.002 B <0.002 T 0.002 X 0.002 GPB-1 (0-2) GPB-1 (2-4) 3/26/97 3/26/97 # 40.002 X 40.002 X 40.002 B <0.002 T 0.002 E <0.002 X 0.002 3/26/97 3/26/97 # 40.002 × 60.002 × 0.002 GPB-1 (4-7') 3/26/97 # <0.002 × <0.002 × <0.002 ASPHALT CURRENT UST S-1 S-14 (11.5) 9/22/94 B <0.002 T <0.002 E <0.002 X 0.003 S-106 GPB-4 DRAINAGE DITCH \$-17(3.5) 9, 294 3 0.002 1 <0.002 × <0.002 ×m + w 9/28/94 9/28/94 B 0.004 T 0.007 T 0.007 E <0.002 S-28 (3') 9/28/94 5643 GPB-1 # 0.008 × 0.01 S-20 (3') 9/28/94 S-9 (13.5) 9/22/94 8 0.002 1 <0.002 E <0.002 X <0.002 \$-28R (12')
4/8/03

B <0.002
T <0.002
E <0.002
X <0.002 SHELL STATION B 0.003 T 0.002 X 40.002 **143RD STREET** BRASSY MREA 5-17 (3') 9/28/94 S-18 (3') 9/28/94 B 0.079 T 0.023 E 0.007 X 0.02 S-6 (13.5) 9/21/94 B 0.006 T <0.002 E <0.002 X <0.002 ×π⊣p S-19 (3') 9/28/94 0,049 0,002 40,002 0,003 S-11 (11.5) 9/22/94 B 0.002 T 0.004 E <0.002 X 0.018 S-10 S-27 (3') 9/28/94 GPB-3 2242 S-4 (13.5) 9/21/94 B 0.004 T <0.002 E <0.002 X 0.004 S-27R (14) 4/8/03 B <0.002 T <0.002 E <0.002 X <0.002 DRAINAGE DITCH \$-5 (11.5) 9/21/94 B 0.002 T 0.002 E <0.002 X <0.002 B 0.002 T <0.002 E <0.002 X 0.004 S-1 (13.5) 9/20/94 GPB-3 (10-13) 3/26/97 40.002 40.002 40.002 S-3 (11.5) 9/21/94 B 0.002 T <0.002 E <0.002 X 0.002 \$-2 (13.5') 9/20/94 8 <0.002 1 0.005 E 0.003 X 0.019 S-23 (3) 9/28/94 B 0.005 T 0.029 5 25 (3°) 9/28/94 GPB-2 (0-2) GF -2 (- 4) 0.004 0.004 0.008 \$0.002 \$0.002 B 0.002 + 0.002 × 0.002 B 0.002 T 40.002 E 40.002 X 0.003 3/26/97 3/26/97 3/26/97 S-13 (13.5) 9/22/94 S.7 (11.5) 9/21/94 S-21 (3') 9/28/94 S-26 (3') 9/28/94 40.002 40.002 7.002 0.002 <0.002 -0.002 0.003 0.005 <0.002 0.004 X 60,002 X 60,002 \$-8 (13.5') 9/21/94 8 <0.002 1 <0.002 E <0.002 X <0.002 # <0.002 # <0.002 X 0.004 S-16 (11.57) 9/22/94 B 0.003 → 0.003 × <0.002 × <0.002 S-12 (11.5) 9/23/94 S-22 (3') 9/28/94 0.004 40.002 0.002 NOT A LEGAL SURVEY, DRAWING BASED ON DOCUMENTATION PROVIDED BY SHELL OIL PRODUCTS US AND FIELD NOTES BY NESA PERSONNEL. ALL LOCATIONS ARE APROXIMATE. DRAWN BY: JRS DATE: 7/16/03 CAD: SA0403.DWG SOIL CONCENTRATION MAP 2001046460 SHELL SERVICE STATION ORLAND PARK, ILLINOIS 14301 S. WOLF ROAD LL CONCENTRATIONS mg/kg PROPERTY BOUNDARY FIGURE 1 BENZENE
TOLUENE
TOTAL XYLENES
NOT DETECTED SOIL SAMPLE LOCATION SOIL BORING LOCATION EGEND #137148 MONITORING WELL LOCATION **EXCAVATION EXTENTS** NESA SCALE IN FEET REVIEWED BY: PKM DATE: 7/16/03 PROJECT: 03065 NESA &
ASSOCIATES, INC.
BURR RIDGE, IL . ყ

0401632082 Page: 3 of 8

THE NORTH 213 FEET OF THE LEST 200 FEET OF THE NORTH 173 FEET OF THE WEST 17 ACRES OF THE NORTH 60 ACRES OF THE NORTH VEST 1/6 OF SECTION 8. TOWNSHIP 36 MORTH, RANGE 12 EAST OF THE THIRD PRINCIPAL HERIDIAN, (EXCEPT THE NORTH 33 FEET THEREOF USFD FOR THE SOUTH 1/2 OF 143RD STREET AND EXCEPT THE VEST 50 FEET LYLREOF TAKEN FOR THE EAST 1/2 OF THE MOLF BOLD AS MEASURED FROM THE NORTH WIRE OF SAID NORTH WEST 1/4), IN COOK COURTY, ILLINDIS.



0401632082 Page: 4 of 8

UNOFFICIAL COPY



ILLINOIS ENVIRONMENTAL PROTECTION AGENCY

1021 NORTH GRAND AVENUE EAST, P.O. BOX 19276, SPRINGFIELD, ILLINOIS 62794-9276, 217-782-3397 JAMES R. THOMPSON CENTER, 100 WEST RANDOLPH, SUITE 11-300, CHICAGO, IL 60601, 312-814-6026

ROD R. BLAGOJEVICH, GOVERNOR

RENEE CIPRIANO, DIRECTOR

217/782-6762

CERTIFIED MAIL 7002 3150 0000 1227 4255

DEC 18 2003

Shell Oil Products US Attention: John Robbins 603 Diehl Road, Suite 103 Naperville, Illingis 60563

Re: LPC 0312315038 -- Cook County Orland Park/ She'l Service Station #137148 14301 South Wolf Road Incident #942158 LUST Technical File

Dear Mr. Robbins:

The Illinois Environmental Protection Agency (Dlinois EPA) has reviewed the High Priority Corrective Action Completion Report submitted for the above-referenced incident. This information is dated August 20, 2003 and was received by the Illinois EPA on August 21, 2003. Citations in this letter are from the Environmental Protection Act (Act) and 35 Illinois Administrative Code (35 Ill. Adm. Code).

The High Priority Corrective Action Completion Report and associated Professional Engineer Certification indicate corrective action for the above-referenced site v. 22 conducted in accordance with the Corrective Action Plan approved by the Illinois EPA. The Corrective Action Completion Report demonstrates that the requirements of Section 57/(c)(1)(E) of the Act and 35 Ill. Adm. Code 732.409(a)(2) have been satisfied.

Based upon the certification by Patrick Haire, a Licensed Professional Engineer, and cursuant to Section 57.10 of the Act (415 ILCS 5/57.10), your request for a no further remediation determination is granted under the conditions and terms specified in this letter.

Issuance of this No Further Remediation Letter (Letter), based on the certification of the Licensed Professional Engineer, signifies that: (1) all statutory and regulatory corrective action requirements applicable to the occurrence have been complied with; (2) all corrective action concerning the remediation of the occurrence has been completed; and (3) no further corrective action concerning the occurrence is necessary for the protection of human health, safety, and the environment. Pursuant to Section 57.10(d) of the Act, this Letter shall apply in favor of the following parties:

12/23/07 cc: P. Mc Donnell, Nesa

ROCKFORD – 4302 North Main Street, Rockford, IL 61103 – (815) 987-7760

ELGIN – 595 South State, Elgin, IL 60123 – (847) 608-3131

DES PLAINES – 9511 W. Harrison St., Des Plaines, IL 60016 – (847) 294-4000
PEORIA – 5415 N. University St., Peoria, IL 61614 – (309) 693-5463 BUREAU OF LAND - PEORIA - 7620 N. University St., Peoria, IL 61614 - (309) 693-5462

SPRINGFIELD - 4500 S. Sixth Street Rd., Springfield, IL 62706 - (217) 786-6892

CHAMPAIGN - 2125 South First Street, Champaign, IL 61820 - (217) 278-5800

COLLINSVILLE - 2009 Mall Street, Collinsville, IL 62234 - (618) 346-5120 MARION - 2309 W. Main St., Suite 116, Marion, IL 62959 - (618) 993-7200

0401632082 Page: 5 of 8

UNOFFICIAL COPY

Page 2

- 1. Shell Oil Products US, the owner or operator of the underground storage tank system(s).
- 2. Any parent corporation or subsidiary of such owner or operator.
- 3. Any co-owner or co-operator, either by joint tenancy, right-of-survivorship, or any other party sharing a legal relationship with the owner or operator to whom the Letter is issued.
- 4. Any holder of a beneficial interest of a land trust or intervivos trust whether revocable or irrevocable.
- 5. Any meagagee or trustee of a deed of trust of such owner or operator.
- 6. Any successor-in-interest of such owner or operator.
- 7. Any transferee of such owner or operator whether the transfer was by sale, bankruptcy proceeding, partition, dissolution of marriage, settlement or adjudication of any civil action, charitable gift, or bequest.
- 8. Any heir or devisee of such owner or operator.

This Letter and all attachments, including but not limited to the Leaking Underground Storage Tank Environmental Notice, must be filed within 45 days of receipt as a single instrument with the Office of the Recorder or Registrar of Titles in the county in which the above-referenced site is located. This Letter shall not be effective until officially recorded by the Office of the Recorder or Registrar of Titles of the applicable county in accordance with Illinois law so it forms a permanent part of the chain of title for the above-referenced property. Within 30 days of this Letter being recorded, an accurate and official copy of this Letter, as recorded, shall be obtained and submitted to the Illinois EPA. For recording purposes, it is recommended that the Leaking Underground Storage Tank Environmental Notice of this Letter be the first page of the instrument filed.

CONDITIONS AND TERMS OF APPROVAL

LEVEL OF REMEDIATION AND LAND USE LIMITATIONS

1. The remediation objectives for the above-referenced site, more particularly described in the Leaking Underground Storage Tank Environmental Notice of this Letter, were established in accordance with the requirements of the Tiered Approach to Corrective Action Objectives (35 Ill. Adm. Code 742) rules.

0401632082 Page: 6 of 8

UNOFFICIAL COPY

Page 3

- 2. As a result of the release from the underground storage tank system(s) associated with the above-referenced incident, the above-referenced site, more particularly described in the attached Leaking Underground Storage Tank Environmental Notice of this Letter, shall not be used in a manner inconsistent with the following land use limitation: There are no land use limitations.
- 3. The land use limitation specified in this Letter may be revised if:
 - a. Further investigation or remedial action has been conducted that documents the attainment of objectives appropriate for the new land use; and
 - b. A new No Further Remediation Letter is obtained and recorded in accordance with Title XVII of the Act and regulations adopted thereunder.

PREVENTIVE, ENGINEERING, AND INSTITUTIONAL CONTROLS

4. Preventive:

Prior to come encement of any future excavation and/or construction in or near the contaminated zone of the remediation site, a safety plan for this remediation site is required that is consistent with National Institute for Occupational Safety and Health Guidance Manual for Hazardous Waste Site Activities; Occupational Safety and Health Administration regulations, particularly in 23 CTR 1910 and 1926; state and local regulations; and other U.S. EPA guidance as provided. At a minimum, the plan should address possible worker exposure if any future excavation and construction activities occur within the contaminated soil.

Engineering:

A concrete/asphalt that is sufficient in thickness to inhibit the inhalation and ingestion of the contaminated media must remain over the contaminated soil as outlined in the attached Site Base Map. This concrete/asphalt is to be properly maintained as an engine red barrier to inhibit inhalation and ingestion of the contaminated media.

Institutional:

This Letter shall be recorded as a permanent part of the chain of title for the above-referenced site, more particularly described in the attached Leaking Underground Storage Tank Environmental Notice of this Letter.

5. Failure to establish, operate, and maintain controls in full compliance with the Act, applicable regulations, and the approved Corrective Action Plan, if applicable, may result in voidance of this Letter.

OTHER TERMS

0401632082 Page: 7 of 8

UNOFFICIAL COPY

Page 4

- 6. Any contaminated soil or groundwater removed or excavated from, or disturbed at, the above-referenced site, more particularly described in the Leaking Underground Storage Tank Environmental Notice of this Letter, must be handled in accordance with all applicable laws and regulations under 35 Ill. Adm. Code Subtitle G.
- 7. Further information regarding the above-referenced site can be obtained through a written request under the Freedom of Information Act (5 ILCS 140) to:

Illinois Environmental Protection Agency Attention: Freedom of Information Act Officer Bureau of Land - #24 1021 North Grand Avenue East Post Office Pox 19276 Springfield, IL 02794-9276

- 8. Pursuant to 35 Ill. Adm. Code 132.704, should the Illinois EPA seek to void this Letter, the Illinois EPA shall provide notice to the owner or operator of the leaking underground storage tank system(s) associated with the above-referenced incident and the current title holder of the real estate on which the tanks were located, at their last known addresses. The notice shall specify the cause for the voidance, explain the provisions for appeal, and describe the facts in support of the voidance. Specific acts or omissions that may result in the voidance of this Letter include, but shall not be limited to:
 - a. Any violation of institutional controls or industrial/commercial land use restrictions;
 - b. The failure to operate and maintain preventive or engineering controls or to comply with any applicable groundwater monitoring plan,
 - c. The disturbance or removal of contamination that has been left in relace in accordance with the Corrective Action Plan or Completion Report;
 - d. The failure to comply with the recording requirements for the Letter;
 - e. Obtaining the Letter by fraud or misrepresentation; or
 - f. Subsequent discovery of contaminants, not identified as part of the investigative or remedial activities upon which the issuance of the Letter was based, that pose a threat to human health or the environment.

0401632082 Page: 8 of 8

UNOFFICIAL COPY

Page 5

Submit an accurate and official copy of this Letter, as recorded, to:

Illinois Environmental Protection Agency Bureau of Land - #24 Leaking Underground Storage Tank Section 1021 North Grand Avenue East Post Office Box 19276 Spring field, IL 62794-9276

If you have any questions or need further assistance, please contact the Illinois EPA project manager, James R. Molcom, III, at 217/524-9140.

Sincerely,

Harry A. Chappel, P.E.

Unit Manager

Leaking Underground Storage Tank Section

Division of Remediation Management

Bureau of Land

HAC: jrm

Attachments: Leaking Underground Storage Tank Environmental Notice 974's Office

Site Map

Legal Description

cc:

NESA

Division File