UNOFFICIAL COPY

RECORDING COVER SHEET

MAIL TO:

Bradley A. Smith
Neal& Leroy LLC
20 S Clark Street Ste 2050
Chicago Illinois 60603

PREPARER: Bradley A. Smith

Neal & Letoy LLC
20 S Clark Street Ste 2050

Chicago Illinois 69603



Doc# 2134119013 Fee ≇88.00

RHSP FEE:\$9.00 RPRF FEE: \$1.00

KAREH A. YARBROUGH COOK COUNTY CLERK

DATE: 12/07/2021 10:53 AM PG: 1 OF 24

FOR RECORDERS OFFICE USE ONLY

DESCRIPTION OF ATTACHED INSTRUMENT:

NO FURTHER REMEDIATION LETTER

PIN NO.:

12-08-100-006-8001 (partisi)

ADDRESS:

O'Hare Building Satellite Fuel Farm, General Site Boundary

O'Hare International Airport, Chicago IL 60666

LEGAL DESCRIPTION:

THAT PART OF THE O'HARE INTERNATIONAL AIRPORT PROPERTY ACQUIRED AS ORCHARD PLACE AIRPORT AND LOCTED IN THE SOUTHWEST QUARTER OF SECTION 31, TOWNSHIP 41 NORTH, RANGE 12 EAST OF THE THIRD PRINCIPAL MERIDIAN IN COOK COUNTY, ILLINOIS DESCRIBED AS FOLLOWS:

THE SOUTHEAST QUARTER OF SECTION 8 TOWNSHIP 40 NORTH, KANGE 12, EAST OF THE THIRD PRINCIPAL MERIDIAN, IN COOK COUNTY, ILLINOIS, TOGETHER WITH ALL RIGHT, TITLE AND INTEREST IN AND TO (VACATED) MANNHELM ROAD AND LAWRENCE AVENUE, IN COOK COUNTY, ILLINOIS.

2134119013 Page: 2 of 24



LLINE EN FIRONMEATAL PROTECTYON AGENCY

1021 NORTH GRAND AVENUE EAST, P.O. BOX 19276, SPRINGFIELD, ILLINOIS 62794-9276 · (217) 782-3397

JB PRITZKER, GOVERNOR

JOHN J. KIM, DIRECTOR

217-524-3300

NOV 02 2021

NOV 15 2021 BY: Qq4 CERTIFIED MAIL
7020 1810 0001 8769 3667

Aaron Frame

Chicago Department of Aviation 10510 West Zemke Road Chicago, Illinois 60666-5038

Re:

0316006019 - Cook County

Chicago Department of Aviation

Chicago O'Lere International Airport Building 988 (Freek Rack Facility) Leaking UST Incident 20210139 Leaking UST Technical File

Dear Mr. Frame:

The Illinois Environmental Protection Agency (Illinois EPA) has reviewed the May 12, 2021 45-Day Report and Corrective Action Completion Report and supplemental information. This information was prepared by Environmental Design International Inc. and was received by the Illinois EPA on July 6, 2021 and October 4, 2021. Citations in this letter are from the Environmental Protection Act (415 ILCS 5) (Act) and Title 35 of the Illinois Administrative Code (35 Illinois Administrative Code).

Site information is summarized in Attachment 1 of this letter. The Corrective Action Completion Report is summarized in Attachment 2 of this letter. Sile diagrams and tables are presented in Attachment 3 of this letter.

The Illinois EPA approves the 45 Day Report (35 Illinois Administrative Code 734.505(b) and 734.510(a)). The 45-day reporting requirements of Section 57.6 of the Act and 35 Illinois Administrative Code 734.210(d) have been satisfied.

The Corrective Action Completion Report and the Licensed Professional Geologist Certification submitted pursuant to Section 57.6 of the Act and 35 Illinois Administrative Code 734.135(d) indicate the remediation objectives have been met.

Based upon the certification by Michael K. Fischer, a Licensed Professional Geologist, and pursuant to Section 57.10 of the Act (415 ILCS 5/57.10), your request for a no further remediation determination is granted under the conditions and terms specified in this letter.

Issuance of this No Further Remediation Letter (Letter), based upon the certification of the Licensed Professional Geologist, signifies that (1) all statutory and regulatory corrective action requirements applicable to the occurrence have been complied with, (2) all corrective action

4302 N. Main Street, Rockford, IL 61103 (815) 987-7760 595 S. State Street, Elgin, IL 60123 (847) 608-3131 2125 S. First Street, Champaign, IL 61820 (217) 278-5800 2009 Mall Street Collinsville, IL 62234 (618) 346-5120 9511 Harrison Street, Des Plaines, IL 60016 (847) 294-4000 412 SW Washington Street, Suite D, Peoria, IL 61602 (309) 671-3022 2309 W. Main Street, Suite 116, Marion, IL 62959 (618) 993-7200 100 W. Randolph Street, Suite 4-500, Chicago, IL 60601

2134119013 Page: 3 of 24

UNOFFICIAL COPY

concerning the remediation of the occurrence has been completed, and (3) no further corrective action concerning the occurrence is necessary for the protection of human health, safety, and the environment. Pursuant to Section 57.10(d) of the Act, this Letter shall apply in favor of the following parties:

- 1. Chicago Department of Aviation, the owner or operator of the underground storage tank systems.
- 2. Any parent corporation or subsidiary of such owner or operator.
- 3. Any co-owner or co-operator, either by joint tenancy, right of survivorship, or any other party sharing a legal relationship with the owner or operator to whom the Letter is issued.
- 4. Any holder of a beneficial interest of a land trust or intervivos trust whether revocable or irrevocable.
- 5. Any mortgagee or trustee of a deed of trust of such owner or operator.
- 6. Any successor in interest of such owner or operator.
- 7. Any transferee of such owner or operator whether the transfer was by sale, bankruptcy proceeding, partition, dissolution of marriage, settlement or adjudication of any civil action, charitable gift, or bequest.
- 8. Any heir or devisee of such owner or operator
- 9. An owner of a parcel of real property to the extent that this Letter applies to the occurrence on that parcel.

This Letter and all attachments, including but not limited to the Leaking Underground Storage Tank Environmental Notice, must be filed within 45 days of receipt as a single instrument with the Office of the Recorder or Registrar of Titles in the county in which the above referenced site is located. This Letter shall not be effective until officially recorded by the Office of the Recorder or Registrar of Titles of the applicable county in accordance with Illinois law so it forms a permanent part of the chain of title for the above referenced property. Within 30 days of this Letter being recorded, an accurate and official copy of this Letter, as recorded, shall be obtained and submitted to the Illinois EPA. For recording purposes, it is recommended that the Leaking Underground Storage Tank Environmental Notice of this Letter be the first page of the instrument filed.

CONDITIONS AND TERMS OF APPROVAL

LEVEL OF REMEDIATION AND LAND USE LIMITATIONS

1. The remediation objectives for the above referenced site, more particularly described in the Leaking Underground Storage Tank Environmental Notice of this Letter, were

2134119013 Page: 4 of 24

UNOFFICIAL COPY

established in accordance with the requirements of the Tiered Approach to Corrective Action Objectives (35 Illinois Administrative Code 742) rules.

- 2. As a result of the releases from the underground storage tank systems associated with the above referenced incident, the above referenced site, more particularly described in the attached Leaking Underground Storage Tank Environmental Notice of this Letter, shall not be used in a manner inconsistent with the following land use limitations:
 - There are no land use limitations. a.
- 3. The land use limitations specified in this Letter may be revised if:
 - Further investigation or remedial action has been conducted that documents the a. attainment of objectives appropriate for the new land use.
 - b. A new No Further Remediation Letter is obtained and recorded in accordance with Title XVH of the Act and regulations adopted thereunder.

PREVENTIVE, ENGINEERING AND INSTITUTIONAL CONTROLS

- 4. Preventive:
 - a. None.
- 5. Engineering:
 - None. a.
- 6. Institutional:
- Dh
 Colling
 cthe c' This Letter shall be recorded as a permanent part of the chain of title for the above a. referenced site, more particularly described in the attached Leaking Underground Storage Tank Environmental Notice of this Letter.
- Failure to establish, operate, and maintain controls in full compliance with the Act, 7. applicable regulations, and the approved Corrective Action Plan, if applicable, may result in voidance of this Letter.

OTHER TERMS

Any contaminated soil or groundwater removed or excavated from, or disturbed at, the 8. above referenced site, more particularly described in the Leaking Underground Storage Tank Environmental Notice of this Letter, must be handled in accordance with all applicable laws and regulations under 35 Illinois Administrative Code Subtitle G.

2134119013 Page: 5 of 24

UNOFFICIAL COPY

9. Further information regarding the above referenced site can be obtained through a written request under the Freedom of Information Act (5 ILCS 140) to:

Freedom of Information Act Officer Illinois Environmental Protection Agency Division of Records Management - #16 1021 North Grand Avenue East Post Office Box 19276 Springfield, Illinois 62794-9276

- 10. Pursuant to 35 Illinois Administrative Code 734.720, should the Illinois EPA seek to void this Letter, the Illinois EPA shall provide notice to the owner or operator of the leaking underg ound storage tank systems associated with the above referenced incident and the current time polder of the real estate on which the underground storage tank systems were located, at their lest known addresses. The notice shall specify the cause for the voidance, explain the provisions for appeal, and describe the facts in support of the voidance. Specific acts or omissions that may result in the voidance of this Letter include, but shall not be limited to:
 - a. Any violation of institut onal controls or industrial / commercial land use restrictions.
 - b. The failure to operate and maintain preventive or engineering controls or to comply with any applicable groundwater monitoring plan.
 - c. The disturbance or removal of contamination that has been left in place in accordance with the Corrective Action Plan or Corrective Action Completion Report.
 - d. The failure to comply with the recording requirements for the Letter.
 - e. Obtaining the Letter by fraud or misrepresentation.
 - f. Subsequent discovery of contaminants, not identified as part of the investigative or remedial activities upon which the issuance of the Letter was based. that pose a threat to human health or the environment.

Submit an accurate and official copy of this Letter, as recorded, to:

Illinois Environmental Protection Agency Bureau of Land Leaking Underground Storage Tank Section 1021 North Grand Avenue East Post Office Box 19276 Springfield, Illinois 62794-9276

2134119013 Page: 6 of 24

UNOFFICIAL COPY

Any questions with regard to this letter should be directed to Michael Piggush via telephone (217-782-3101) or electronic mail (michael.piggush@illinois.gov).

Sincerely,

Trent L. Benanti, P.E.

Tutt Bet

Unit Manager

Leaking Underground Storage Tank Section

Bureau of Land

Attachments (1):

- Summary of Site Information. 1.
- 2. Summary of Corrective Action Completion Report.
- Site Diagrams and Tables. 3.
- Leaking Underground Storage Tank Environmental Notice. 4.
- 5. Legal Description.

Copies (4):

- Aaron Frame (Chicago Department of Aviation), aaron.frame@cityofchicago.org. 1.
- 2. Ryan Lane (Chicago Department of Aviation), ryan.lane@cityofchicago.org.
- ation. Scott Dileto (Environmental Design International Inc.), sdileto@envdesigni.com. 3.
- Bureau of Land File. 4.

2134119013 Page: 7 of 24

UNOFFICIAL COPY

Attachment 1

Summary of Site Information


Re: 0316006019 - Cook County
Chicago - Chicago Department of Aviation
Chicago O'Hare International Airport
Building 988 (Truck Rack Facility)
Leaking UST Incident 20210139
Lealing UST Technical File

The basic site information is summarized as follows:

- 1. The site property is an airport.
- 2. Releases have occurred from the following underground storage tank systems:
 - a. The piping associated with five 50,000-gallon jet fuel underground storage tank systems (underground storage tank systems 19 23).
- 3. The indicator contaminants are BETX and PNAs.
- 4. Groundwater has been assumed to be Class I.
- 5. The tanks associated with the piping were previously removed in 1999.
 - a. Leaking UST Incident 990431 was obtained at that time.
 - b. The Illinois EPA issued a No Further Remediation Letter for Leaking UST Incident 990431 on January 11, 2000.
- 6. The underground storage tank system piping was removed from February 8 through 18, 2021 by RW Collins Co. of Chicago, Illinois.
 - a. A total of 3,405 cubic yards of contaminated soil (795 cubic yards of backfill material and 2,610 cubic yards of native soil) were excavated and disposed of from February 9, 2021 through March 29, 2021 by RW Collins Co. of Chicago, Illinois.
 - b. A total of 43 soil samples (soil samples PS-1 PS-18, SS-19 SS-22, and PS-201 PS-221) were obtained from the soil excavation area by Environmental Design International Inc. of Chicago, Illinois.

UNOFFICIAL COPY

- The soil samples were analyzed for BETX, PNAs, and soil moisture content by c. Grace Analytical Lab, Inc. of Berkeley, Illinois with the exception of the following:
 - i. Soil sample PS-221 was not analyzed for PNAs.
- 7. The contaminated soil was disposed of at the Winnebago Landfill in Rockford, Illinois.
- 8. The soil excavation area was backfilled.



2134119013 Page: 9 of 24

UNOFFICIAL COPY

Attachment 2

Summary of Corrective Action Completion Report

Re: 0316006019 - Cook County
Chicago - Chicago Department of Aviation
Chicago O'Hare International Airport
Building 988 (Truck Rack Facility)
Leaking UST Incident 20210139
Lea'ang UST Technical File

The Corrective Action Completion Report is summarized as follows:

- 1. The Corrective Action Completion Report states that soil samples PS-201 PS-212, PS-213 (PNAs only) and PS-214 PS-221 are being used for purposes of closure.
- 2. The Corrective Action Completion Report states that the closure soil samples were not contaminated in excess of the most stringent soil remediation objectives.
- 3. The Corrective Action Completion Report states that groundwater was not encountered in the soil excavation area.
- 4. The Corrective Action Completion Report requests the issuance of a No Further Remediation Letter.

2134119013 Page: 10 of 24

UNOFFICIAL COPY

Attachment 3


Site Diagrams and Tables

Distribution of Cook Carried State of the Co


2134119013 Page: 11 of 24

UNOFFICIAL COPY

Figure 1 - Site Location Map




UNOFFICIAL COPY





ILLINOIS PROFESSIONAL DESIGN FIRM LICENSE NO. 184-001224 CLIENT: CHICAGO DEPARTMENT OF AVIATION
CLIENT: 10510 WEST ZEMEKE ROAD, CHICAGO, IL 60666 Environmental Design International Inc. Civil, Survey, Environmental and Construction Inspection Services 33 W. MONROE STREET, SUITE 1825, CHICAGO, IL 60603 Ph. (312) 345-1400 Fax (312)345-0529


PROJ. No: 1977.001 DATE: 08/31/2021


DRAWN BY: IS APPROVED BY: VR











2134119013 Page: 18 of 24

1964). I SAO CANDERE IN TOTAL THE THROUGH PRESENT PRESENTATION OF THE SAO CANDER PRESENT SHAPE SEARCH SEARC

_	·	_				L				J	(•	E	_					J	7			_ COPY
242021	27,555		(Papa)	1 9	3610 U	122000	0,0017	40151		0.908	g	0.608	0.301	B.	0.196	0.0736	0,164	92.70	£	2.35	1.37	0.0520	0.40\$	2.84	0.416	
1202/146	1259		(mg/kg)		0.00921	\$100000	0.0179	B2756		0.0783	ş	ş	0.0375	9	D.0284	ã	0.0216	ş	ğ	2220	281.0	9	2	127	ę	2
14004	8870		(By,Bu)		800000	101010	0.0152	0 02230		105:0	9	0.662	0.546	620	0.324	0.0005	0.238	6305	ę	5	0.081	4078	0.324	78	0.672	0.822
347001	9519		[[0.00]		0.014	0.00000	D.D161	22100		9	ş	ð	9	9	9	ş	õ	ð	9	0.0619	0.0486	9	Ş	***	₽	2
122160	PS-18		(mg/kg)		0.00972	C. Dalecco	0.0158	\$10.0		ð	g	9	0,0478	452370	0.028	9	0.028	0.0501	Ş	a 000	0.101	9	ę	220	0.0618	# 1907D
1221123	11-50		(By/dus)		0.0879	0,148	0.0228	22,073		9220	g.	8290	0.212	e.TCI	0.102	9	101.0	B.250	9	roşa	0.688	ž	155.0	1.5	0.288	0.720
12/11/20	25.56		(mg/kg)		0.0654	2061	QV.	0,000		1,18	PN	0413	0.524	0.371	Q.328	71800	0.282	£ 55	DN	3	25,1	Saga	191	3	0.675	6475
היוינים	P3-15		(Brydu)	10 mm	0.0128	٥	g	ş		87	9	9590	0,745	0.165	Q.1460	0.0651	101.0	0.246	2	577.0	2,1	anges	437	3,0	6,477	600
SQU1123	P1-5a		Ę		0.00312	P0:04	2	M 100		0.361	9	2	0,842	0.481	0.547	0.146	0,456	7950	Q.	2.38	77'0	e d	181.0	797	ŭ	**
1571/CD	¥.		(mp/hg)		1200		000633	9		1.64	Q	1,48	0,674	2143	0.378	8,108	16.0	2.553	Q	:	2.29	6100	1.08	6.82	108	8
1211121	P\$-12		(møyd)		ę	ð	ž	9	,	4.30	ΩN	12.6	404	1,74	161	0.427	1,57	7.88	QN.	13.3	11.1	952*0	1.21	. R	8.8	
12/01/20	ž		[mg/gi]	120	. B843	ā	ę	-000		7.07	귈)	. PSB	2517	199.0	9	909 Q	g. 854	2	3	188	9	20.4	70.5	1.17	
egetoca.	8.5		(mg/kg)		B.64.94	E10402	ð	0.0754		15.0	Ð	514.0	2.28	H-1	1.0	0.530	1.47	204	QN	ş	32,8	0.520	152	13.8	3.18	2
1501-50	34		(Bydu)		9	ă	ð	90000		13	0.0717	77	1.70	5.35	3.7		2,5	77	CN	9,	\$2,3	toet)	5,05	14.8	3,45	\$
120120	2764		(mg/hg)		0.0366	\$12s	9,00177	20.78		2.48	0.366	1,1	1.65	4.30	4.70	21.12	38, 27	**	Ŋ	40	3 2	8 -1	165	17.4	6.37	150
#DUC3	ş		(mg/kg)		7	1.83	0.00.0	5,		B.16	2	2	14.1	7,14	1.23	2.03	67.9	10.7	Q	×	41	2002	ģ	8	16.3	
1,001-00	ĭ		(mp/hg)	118	E773	613	ğ	9		2	ā	1151	0.719	0.385	D. 4PM	ð	0.426	0.506	Q	*3	3.08	ð	2,61	2,	199	
150120	ž		ĵ,		9	D.Serie	ğ	ā		18.5	QN	10.5	61	7.09	9,51	2.33	7.94	128	Q	31.5	ZX.	2.41	F.M.	8.8	1/84	
COLLOCA	į		î,		0.481	54.0	9	9		ĸ	50	13	HE'E	271	2.97	1860	2.6	80.1	QN	88	879	D 881	17,6	20.	5.8	
150 TGD	58		(p/em)		P	Q.7WY	ą	ę		21.18	30.8	221	57	2.43	2.15	209 1	2.28	**	ç	9	£ >2	6.839	•	13.2	4.56	7.6
1201020	ř		(Psydou)	100000000000000000000000000000000000000	9	3.6	Ð	0.946	10000	1:12	91.3	5.36	18'8	7.00	16,8	122	623	91.8	Q.	18,8	2.62	7.68	106	33.6	12.3	
120120	ř		(Jack		Ť	0.842	0.0403	0.345		483	9	Ī	9619	404	5	172	5,71	5.79	9	20.5	52.2	52	2.01	17.2	11.3	
	Concentrations Background	Cheage	P A	100 miles	ş	ŧ	3	ž		80 5	8	87.0	11	1.3	1.6	99'0	90	1.2	0.2	â	5	8	5	2	=	
	Construction Worker Route Speaks Values for Smil	letelation	(average)	11.22	52	5	7	\$\$	1	1	-	1	1	1	-	-	1	1	1		1	1	1.8)	_ -	
	Construction Work	Ingestion	(marke)		2300	20,000	416 000	41.000	1000	200,000	1	410,000	DZ.1	17	13	1	202	17,000	43	B.'Z	62.000	52	4 100	_	61,000	1
Mone TACO Values	a for South	Inhudelton	D C		2	ş	2	S.S.	***	,	ı	ı	1	-	1		ı	ı	ı		ı	1	240	1	ı	1
ı K	Industrial Commercial Route Specific Values for Soil	Ingestoon	(mg/kg)		ĕ	000'002	410,000	410,000		120,000		810,000	•	9.0	-	-	92	780	979	82,000	82,000	-	41,000		900 19	800
	<u> </u>	Щ	┡		0.17	2	ę	ã		2,900	,	200.08		29	ĸ	-	ŝ	В	7.6	21,000	2,800	2	£	,	21,000	3,308
	Sol Component of Greandwater Ingention Exposure Route Value	Diene	D (AL)		100	2		ã		£5	1	12,000	7	•	•	-	-	8		98,	95	=	ž		000"	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
	! —		Ľ		_			ā			3		acente	•ue.	austra	nyjeus	appens		ALECTE OF	-	- -	Opposers				diperse availab
				AHO)	Bargera	Ethylbanzerv	Toleman	Xylenee, Total	STATE OF THE STATE	Acenaphisese	Acenaphilipera	Antherene	Benzejajantvanene	Berzo(s)pyrene	Berzo(b)Austra	Serco(g.h.)perylane	Senzo(k) Sezrandrem	Chryslen	Dilamaz (a. h) amilio accene	Fluoranthene	Fluorena	Indemo(1,2,3-cq)pyrene	Maph@dwarn	Phanambrens	Pyterix	Press ASS (Consequence of Consequence of Consequenc

2134119013 Page: 19 of 24

Γ	E	T	1-	1,430		L	_	T	\		6		1	F	_				(-	Δ	-	ı	_	COPY
1202/2021	PS-221 (re-sample of PS-213)		(Jagar)		9	9	2	9	**************************************		2	Ð	9	Ż	2	9	g	Q.	2	¥	2	2	۶	ą	ą	ð	
03/16/21	92754		(mg/sp)	7,000	9	9	9	9	70 V		9	ď	9	9	9	ð	9	ĝ	9	9	9	õ	ð	9	9	ð	2
03/18/21	FS-218		13 pt		9	9	9	9	0.00		٩	9	9	9	9	g	9	9	9	9	9	Ð	ð	9	9	9	7
12791/6021	P\$-234		(Dydins		9	2	9	2	1 20		9	9	9	Q.	ş	9	õ	ē	9	9	9	Ē	9	9	ON.	9	2
12,917,0	P8-217		(Dydu)	770	9	9	9	9			9	9	ð	Q	2	7	9	5	9	9	9	ð	9	9	9	9	2
12/91/20	P8-218		E C	100	9	ę	9	ę			9	g	9	g	9	ç	ą	9	9	g	9	9	9	9	9	9	2
12/8/12/0	P8-2:5		(Dydou)		ð	QN.	9	2			2	2	Q	9	9	CIN.	ð	2	9	9	9	Q	Q	Q.	9	9	
03/18/21	HL'S	C	(mg/vgm)	7	9	2	9	9	100		9	P	9	Ð	9	9	9	5	9	9	9	9	9	g	9	õ	2
12/11/0	512-513	1	•		1 tree	ē	9	ş	4		9	9	9	9	9	Ð	9	9	9	2	9	Q.	₽	Q	2	9	-
0.3/16/21	P\$-212		ji Su		9	Š	0	9			2	ç	9	9	9	9	9	õ	ç	2	2	ũ	9	Q	9	9	-
15/5/150	P\$-211		(mg/kg)		9	9	9	g		1	2	9	9	물	ğ	9	9	9	ě	Ž	9	9	9	g	2	9	2
12/51/50	P\$-210		P. Sale	100	9	2	9	9	100000000000000000000000000000000000000	,	Ţ	9	2	QN	9	2	g	Ð	9	ð	9	Q.	9	9	ND.	9	
03/15/24	PS-209	İ	ghyōus	700	9	9	9	9	100		2	ę.	9	QN	2	72	9	Q.	9	9	Q	Q	9	9	9	9	2
03/15/21	P\$-208		(bug),d)	CHEST AND STREET	ð	ş	2	5	900000000000000000000000000000000000000		2	Ş	9	Q	QV	9	Q	9	2	9	9	NO.	£	9	ē	Đ	2
125140	102.44		(mg/ct)		ē	ç	9	9		,	2	9	9	Ð	Q	Ş	9	ð	5	ź	١	1 0	Qv	2	2	Đ	2
03/15/21	PS-208		(mg/kg)		ş	ş	9	ş	200		2	9	2	2	9	9	g	Ð	9	g	9	Ori	2	2	- 4	١,	
12/51/50	BE-Sd		(morkq)	*2.4	g	9	ę	Ď	33333],	2	ð	9	Q	Ş	Ð	Q	Q.	9.	۶	9	Q	2	g	9	0	4
102/15/01	PS-254		(moke)	1000	9	Ę	9	P	200	1	2	9	Ź	QV	2	Ż	9	ž	9	9	9	Q	9	9	ð	ē	
03/15/21	602-944		(Dydnu)	47	9	£	9	2	100 May - 11	9	2	Ş	ġ	g	9	9	ç	S	2	2	ě	9	9	9	Ð	ę	74
12751760	P9-202	1	2	15H25000	5	2	9	2		,	5	ð	9	2	9	ð	ð	Q.	9	9	9	9	9	ð	ē	9	0,0
12/51/00	107%		(DayOut)		9	Đ	ð	£	133	9	Ş	9	Q.	g	9	9	Q	ą	9	9	ð	Q.	9	Š	9	ą	
	Concentrations Bachground Sods*	Chicago	(Byou)		£	, s	5	a,	1		S)	600	22	171	C'I	1,5	1910	66.0	£11	0.2	2,3	1.0	0.64	0,04	1.3	•	Clart's Office
		Intelation	(mg/kg)		2.2	85	-12	5.6		1	'	'	-	-	_	,	_	,	-	-	-	1	ı	t,a	ı	ı	
	Contratection Warmer Route Special	Ingestion	(Dydu)		2300	000 02	410,000	00017	1255 Cons. 12		amia#1	'	610,000	021	11	170	1	1.700	17,000	11	42.500	82,000	170	4,100	1	61,000	DO TO
Mindes TACO Values		malatan	markai		=	400	9	320	100 mg	+	,	1	- 1	ı	1	1	ı	١,	ı	 -	ı	1	1	976	ı	,	
Minor	Inductional Communical Region Specific Values for Soil	Ingestion	(Brydau)		ē	200,000	410,000	410,000	100		20,000	-	610,000	-	8.0	-	,	18	292	9.0	62.000	62,000		41,000	-	000,18	
	_	<u> </u>	-	770.	1,0	ē	æ	150	1000000	+		1	59,000		2	×s	1	Z	8	7.8	21,000	2,900	8	at.	1	21 800	_
	Soil Companies of Droundseaver Ingresson Exposure Route Values	Chast	┞		80		2	š		+		-	12,000	,	-	<u> </u>	1	\$	<u>s</u>		, ex.	989	1	13	,	1 200	Dan I
		·	Ľ		ļ-	1	-	- T-	100 S	-	+	3	ï	Chomba	1474	triffiante	erytene	august 1	,	historie	_	_	Chinese	***	•		elgpa (Acco),
	_			Xala	Berzele	Elhykkangent	Talwers	Kyfener, Total	*		Acerephthene	Acessprinylene	Antimonna	Banno(a)anthracens	Benzeja)pyrane	Ben70(b) Muorumban	Benzalg.P. (Ipperytens	Berze(s)fuprambers	Chyperia	Dibenz(a ti)anthracene	Flucranthens	Fluorene	Indemo(12.3-cd)pyrene	Neghthalane	Preventivens	Pyrene	Sand Constant of L

2134119013 Page: 20 of 24

UNOFFICIAL COPY

Attachment 4

Leaking Underground Storage Tank Environmental Notice

Property of Cook County of Serious County of Ser

2134119013 Page: 21 of 24

UNOFFICIAL COPY

PREPARED BY:

Name:

Aaron Frame

Chicago Department of Aviation

Site Address:

Chicago O'Hare International Airport

Building 988 (Truck Rack Facility)

Chicago, Illinois 60666

RETURN TO:

Name:

Aaron Frame

Chicago Department of Aviation

Mailing Address:

10510 West Zemke Road Chicago, Illinois 60666-5038

(THE ABOVE SPACE FOR RECORDER'S OFFICE)

LEAKING UNDERGROUND STORAGE TANK ENVIRONMENTAL NOTICE

THE OWNER AND / OR OPERATOR OF THE LEAKING UNDERGROUND STORAGE TANK SYSTEMS ASSOCIATED WITH THE RELEASE REFERENCED BELOW, WITHIN 45 DAYS OF RECEIVING THE NO FURTHER CEMEDIATION LETTER CONTAINING THIS NOTICE, MUST SUBMIT THIS NOTICE AND THE REMAINDER OF THE NO FURTHER REMEDIATION LETTER TO THE OFFICE OF THE RECORDER OR REGISTRAR OF TITLES OF COOK COUNTY IN WHICH THE SITE DESCRIBED BELOW IS LOCATED.

Illinois EPA Number: 0316006019 Leaking UST Incident: 20210139

The Chicago Department of Aviation, the owner and / or operator of the leaking underground storage tank systems associated with the above referenced incident, whose mailing address is 10510 West Zemke Road, Chicago, Illinois, 60666-5038, has performed investigative and / or remedial activities for the site identified as follows:

- 1. Legal Description or Reference to a Plat Showing the Boundaries: Please refer to Attachment 5 of this Letter.
- 2. Common Address: Chicago O'Hare International Airport, Building 988 (Truck Rack Facility), Chicago, Illinois, 60666.
- 3. Real Estate Tax Index / Parcel Index Number: Part of 12-08-100-006-8001.
- 4. Site Owner: Chicago Department of Aviation.
- 5. Land Use Limitations: There are no land use limitations.
- 6. See the attached No Further Remediation Letter for other terms.

2134119013 Page: 22 of 24

UNOFFICIAL COPY

Attachment 5

Legal Description

Oct MONISHING HOW TO HOW THE SHARE HOUSE IS HERE TO HOUSE IN THE SHARE OZIMOS ZOGO II. OSIMOS NOSIMOS
2134119013 Page: 23 of 24

UNOFFICIAL COPY

LEGAL DESCRIPTION

Site Name:

O'Hare Building Satellite Fuel Farm, General Site Boundary

Site Address/Limits: O'Hare International Airport, Chicago, IL 60666

County:

Cook

PIN:

12-08-100-006-8001 (pt.)

THAT PART OF THE O'HARE INTERNATIONAL AIRPORT PROPERTY ACQUIRED AS ORCHARD PLACE AIRPORT AND LOCATED IN THE SOUTHWEST QUARTER OF SECTION 31, TOWNSHIP 41 NORTH, RANGE 12 EAST OF THE THIRD PRINCIPAL MERIDIAN, IN COOK COUNTY, ILLINOIS DESCRIBED AS FOLLOWS:

THE SOUTHEAST QUARTER OF SECTION 8 TOWNSHIP 40 NORTH, RANGE 12, EAST OF THE THIRD PRINCIPAL MERIDIAN, IN COOK COUNTY, ILLINOIS, TOGETHER WITH ALL RIGHT, TITLE AND INTEREST IN AND TO (VACATED) MANNHEIM ROAD AND LAWRENCE AVENUE, IN COOK COUNTY JULINOIS.

204 COUNTY CIEPTS OFFICE PART OF PIN: 12-08-100-006-8001

RECORDING REQUIREMENTS FOR NO FURTHER REMEDIATION LETTERS

Introduction

The Illinois Environmental Protection Agency's (Illinois EPA) Bureau of Land/Leaking Underground Storage Tank Section issues a No Further Remediation (NFR) Letter after a demonstration of compliance with Title XVI of the Environmental Protection Act and applicable regulations is made. The NFR Letter signifies that: (1) all statutory and regulatory corrective action requirements applicable to the occurrence have been complied with, (2) all corrective action concerning the remediation of the occurrence has been completed, and (3) no further corrective action concerning the occurrence is necessary so long as the site is used in accordance with the terms and conclusions of the NFR Letter.

Significance

When properly recorded, the NTR Letter holds legal significance for all applicable parties outlined at Section 57.10(d) of the Environmental Protection Act. (See 415 ILCS 5/57.10(d).) If not properly recorded, the Illinois EPA *will* take steps to void the NFR Letter in accordance with the regulations.

Duty to Record

The duty to record the NFR Letter is mandatory. You must submit the NFR Letter, with a copy of any applicable institutional controls proposed as part of a corrective action completion report, to the Office of the Recorder or the Registrar of Titles of the county in which the site is located within 45 days after receipt of the NFP Letter. You must record the NFR Letter and any attachments. The NFR Letter shall be filed in accordance with Illinois law so that it forms a permanent part of the chain of title to ensure current and future users of the property will be informed of the conditions and terms of approval including level of remediation; land use limitations; and preventive, engineering, and institutional controls. A certified or otherwise accurate and official copy of the NFR Letter and any attachments, as recorded, must be submitted to the Illinois EPA. Failure to record the NFR Letter voidable.

For More Information

Please refer to the Tiered Approach to Corrective Action Objectives (TACO) fact sheet entitled *No Further Remediation Letters*, which is available from the Illinois EPA by calling (217) 524-3300 or by accessing it on the Illinois EPA Web site at https://www2.illinois.gov/epa/topics/cleanup-programs/taco/fact-sheets/Pages/no-further-

remediation-letters.aspx.