# **UNOFFICIAL COPY**

#### PREPARED BY:

Name:

Monique Durham

Illinois Bell Telephone/ SBC Services, Inc.

Address:

225 West Randolph Street

Chicago, IL 60606

**RETURN TO:** 

Name:

Monique Durham

Ili 10is Bell Telephone/ SBC Services, Inc.

Address:

308 South Akard, Suite 900

Dallas, TX 75202

(THE ABOVE SPACE FOR RECORDER'S OFFICE)

Doc#: 0600319022 Fee: \$32.50

Eugene "Gene" Moore RHSP Fee:\$10.00

Cook County Recorder of Deeds Date: 01/03/2006 11:19 AM Pg: 1 of 5

LEAKING UNDER GROUND STORAGE TANK ENVIRONMENTAL NOTICE

THE OWNER AND/OR OPERATOR OF THE LEAKING UNDERGROUND STORAGE TANK SYSTEM(S) ASSOCIATED WITH THE RELEASE REFUNCED BELOW, WITHIN 45 DAYS OF RECEIVING THE NO FURTHER REMEDIATION LETTER CONTAINING THIS NOTICE, MUST SUBMIT THIS NOTICE AND THE REMAINDER OF THE NO FURTHER REMEDIATION LETTER TO THE OFFICE OF THE RECORDER OR REGISTRAR OF TITLES OF COOK COUNTY IN WHICH THE SITE DESCRIBED BELOW IS LOCATED.

Illinois EPA Number: 0316285109

LUST Incident No.: 902100

SBC Services, Inc., Monique Durham, the owner and/or operator of the leaking underground storage tank system(s) associated with the above-referenced incident, whose address is 308 South Akard, Suite 900, Dallas, Texas, has performed investigative and/or remedial activities for the site identified as follows and depicted on the attached Site Base Map:

- Legal Description or Reference to a Plat Showing the Boundaries: Lot 2 3 and 4 in Block 41 in 1. Original Town of Chicago Cook County, Illinois
- Common Address: 225 West Randolph Street, Chicago, Illinois 2.
- Real Estate Tax Index/Parcel Index Number: 17-09-443-001, 17-09-443-002, 17-09-443-003, 17-3. 09-443-004 and 17-09-443-005
- Site Owner: Illinois Bell/ SBC Services, Inc., Monique Durham 4.
- Land Use Limitation: There are no land use limitations. 5.
- See the attached No Further Remediation Letter for other terms. 6.

BJD

Attachment: Site Base Map

0600319022 Page: 2 of 5

# INOFFICIA Illinois Environmental Protection



1021 North Grand Avenue East, P.O. Box 19276, Springfield, Illinois 62794-9276 – (217) 782-3397 James R. Thompson Center, 100 West Randolph, Suite 11-300, Chicago, IL 60601 – (312) 814-6026

ROD R. BLAGOJEVICH, GOVERNOR

DOUGLAS P. SCOTT, DIRECTOR

217/782-6762

CERTIFIED MAIL

7004 2510 0001 8655 1953

DEC 16 2005

Illinois Bell Telephone/ SBC Services, Inc. Monique Darham 308 South Akaro, Suite 900 Dallas, TX 75202

Re:

LPC #0316235169 -- Cook County Chicago/ Illinois 36 il Telephone 225 West Randolph Street LUST Incident No. 9621 JC LUST Technical File

Dear Ms. Durham:

The Illinois Environmental Protection Agency (Illinois EPA) has reviewed the Corrective Action Completion Report submitted for the above-referenced incident. This information is dated September 27, 2005 and was received by the Illinois EPA on October 1, 2005. Additional information was dated November 2, 2005 and was received by the Illinois EPA on November 3, 2005. Citations in this letter are from 35 Illinois Administrative Code (35 Ill. Adm. Code).

The Corrective Action Completion Report and the Professional Erginger Certification submitted pursuant to 35 Ill. Adm. Code 731 indicate remediation has been successfully completed.

Based upon the certification by John S. Esser, a Licensed Professional Engineer, and based upon other information in the Illinois EPA's possession, your request for a no further remediation determination is granted under the conditions and terms specified in this letter.

Issuance of this No Further Remediation Letter (Letter), based on the certification of an Licensed Professional Engineer, signifies that: (1) all statutory and regulatory corrective action requirements applicable to the occurrence have been complied with; (2) all corrective action concerning the remediation of the occurrence has been completed; and (3) no further corrective action concerning the occurrence is necessary for the protection of human health, safety, and the environment. This Letter shall apply in favor of the following parties:

- SBC Services, Inc., Monique Durham, the owner or operator of the underground storage tank 1.
- Any parent corporation or subsidiary of such owner or operator. 2.

0600319022 Page: 3 of 5

# **UNOFFICIAL COPY**

#### Paul !

- Any co-owner or co-operator, either by joint tenancy, right-of-survivorship, or any other party sharing a legal relationship with the owner or operator to whom the Letter is issued.
- Any holder of a beneficial interest of a land mist or inter-vivos trust whether revocable or interescable.
- 3. An anongagee or mistee of a deed of trisc of such owner or operator
- o An am cessor-in-interest of such owner or operator
- Any transferse of such owner or operator whether the transfer was by sale, bankruptcy proceeding partition, dissolution of marriage, settlement or adjudication of any civil action, charitable gift, or beques:
- 8 Any heat or devisee of such cannot or operator

This Letter and all attachments, including but not limited to the Leaking Underground Storage Tank Environmental Motice, must be filed within 15 days of receipt as a single instrument with the Office of the Recorder or Registrar of Titles in the county in which the above-referenced site is located. This Letter shall not be effective until officially recorded by the Office of the Recorder or Registrar of Titles of the applicable county in accordance with Illinois law so it forms a permanent part of the chain of title for the above-referenced property. Within 30 days of this Letter being recorded, an accurate and official copy of this Letter, as recorded, shall be obtained and submitted to the Illinois EPA. For recording purposes, it is recommended that the Leaking Underground Storage Tank Environmental Notice of this Letter be the first page of the instrument filed.

### CONDITIONS AND TERMS OF APPROVA

### LEVEL OF REMEDIATION AND LAND USE LIMITATIONS

- The remediation objectives for the above-referenced site, more particularly descrit ed in the Leaking Underground Storage Tank Environmental Notice of this Letter, were carrolished in accordance with the requirements of the Tiered Approach to Corrective Action Objectives (35 III. Adm. Code 742) rules
- As a result of the release from the underground storage tank system(s) associated with the above-referenced incident, the above-referenced site, more particularly described in the attached Leaking Underground Storage Tank Environmental Notice of this Letter, shall not be used in a manner unconsistent with the following land use limitation: There are no land use limitations.
- 3. The land use limitation specified in this Letter may be revised if
  - a surther suvestigation or remedial action has been conducted that documents the attainment of objectives appropriate for the new land use, and

0600319022 Page: 4 of 5

# **UNOFFICIAL COPY**

#### Page 3

A new No Further Remediation Letter is obtained and recorded in accordance with Title b. XVII of the Act and regulations adopted thereunder.

## PREVENTIVE, ENGINEERING, AND INSTITUTIONAL CONTROLS

Preventive: 4.

None.

Engineering:

None.

Institutional:

This Letter shall be recorded as a permanent part of the chain of title for the above-referenced site, more particularly described in the attached Leaking Underground Storage Tank Environmental Notice of this Letter.

Failure to establish, operate, and maintain controls in full compliance with the Act, applicable regulations, and the aport ved Corrective Action Plan may, if applicable, result in voidance of this 5. Letter.

#### OTHER TERMS

- Any contaminated soil or groundwater removed or excavated from, or disturbed at, the above-6. referenced site, more particularly described in the Leaking Underground Storage Tank Environmental Notice of this Letter, must be nondled in accordance with all applicable laws and regulations under 35 Ill. Adm. Code Subtitle G.
- Further information regarding the above-referenced site can be obtained through a written request 7. under the Freedom of Information Act (5 ILCS 140) to: -16/4'S OFFICE

Illinois Environmental Protection Agency Attention: Freedom of Information Act Officer Bureau of Land - #24 1021 North Grand Avenue East Post Office Box 19276 Springfield, IL 62794-9276

- Should the Illinois EPA seek to void this Letter, the Illinois EPA shall provide notice to the owner 8. or operator of the leaking underground storage tank(s) associated with the above-referenced incident and the current title holder of the real estate on which the tanks were located, at their last known addresses. The notice shall specify the cause for the voidance, explain the provisions for appeal, and describe the facts in support of the voidance. Specific acts or omissions that may result in the voidance of this Letter include, but shall not be limited to:
  - Any violation of institutional controls or industrial/commercial land use restrictions; a.
  - The failure to operate and maintain preventive or engineering controls or to comply with b. any applicable groundwater monitoring plan;

0600319022 Page: 5 of 5

## **UNOFFICIAL CC**

#### Page 4

- The disturbance or removal of communation that has been left in place in accordance with the Corrective Action Plan or Completion Report;
- The failure to comply with the recording requirements for the Letter;
- Obtaining the Letter by fraud or misrepresentation; or
- volvsequent discovery of contaminants, not identified as part of the investigative or remedial activities upon which the issuance of the Letter was based, that pose a threat to rman health or the environment

Submit an accurate and official copy of this Lette: as recorded, to

Minois Environmental Protection Agency

Sureau of Land 124

Leaking Underground Storage Tank Section

1071 North Grand Avenue East

Post Office Box 19276

Springfield. IL 62794.927

Mase co. if you have any questions or need further assistance please contact the illinois EPA project manager. Brad Dilbairis, at (217) 785-8378

Sincerely.

Hernando A. Albarracia

Unit Manager

Leaking Underground Storage Tank Section

Division of Remediation Management

Bureau of Land

HAA:BID' NFR.doc

Leaking Underground Storage Tank Environmental Notice Attachments.

Site Base Map

STS Consultants

Division Pile