UNOFFICIAL COPY



Cook County Recorder of Deeds Date: 01/18/2011 03:32 PM Pg: 1 of 10

1101849087 Fee: \$54.00 Eugene "Gene" Moore RHSP Fee:\$10.00

PREPARED BY:

Name:

Mark Costa

Signature Flight Support

Address: 1126 South Milwaukee Avenue

Wheeling, IL 60090

RETURN TO:

Name:

Mark Costa

Signature Flight Support

Address:

1126 South M'I waukee Avenue

Wheeling, IL 62090

(THE ABOVE SPACE FOR RECORDER'S OFFICE)

LEAKING UNDERGROUND SOCRAGE TANK ENVIRONMENTAL NOTICE

THE OWNER AND/OR OPERATOR OF THE LEAKING UNDERGROUND STORAGE TANK SYSTEM(S) ASSOCIATED WITH THE RELEASE REFERENCED BELOW, WITHIN 45 DAYS OF RECEIVING THE NO FURTHER REMEDIATION LETTER CONTAINING THIS NOTICE, MUST SUBMIT THIS NOTICE AND THE REMAINDER OF THE NO FURTHER REMEDIATION LETTER TO THE OFFICE OF THE RECORDER OR REGISTRAR OF TITLES OF COOK COUNTY IN WHICH THE SITE DESCRIBED BELOW IS LOCATED.

Illinois EPA Number: 0314977669 Leaking UST Incident No.: 20071356

Signature Flight Support, the owner and/or operator of the leaking underground storage tank system(s) associated with the above-referenced incident, whose address is 1126 South Milwaukee Avenue, Wheeling, Illinois, has performed investigative and/or remedial activities for the site identified as follows and depicted on the attached Site Base Map:

Legal Description or Reference to a Plat Showing the Boundaries: BEGINNING 1. THENCE NORTH ALONG THE CENTER LINE 100 FEET THENCE SOUTH 64° 29' 00" WEST 209.50 FEET THENCE EAST ALONG THE SOUTH LINE OF LOT 1 A DISTANCE OF 232.14 FEET TO THE POINT OF BEGINNING, AND EXCEPT THAT PART COMMENCING AT THE INTERSECTION OF THE NORTH LINE OF LOT 2 AND THE CENTERLINE OF MILWAUKEE AVENUE THENCE SOUTHEASTERLY ALONG THE CENTERLINE 48.50 FEET THENCE SOUTH 64° 29' 00" WEST TO THE SOUTHWESTERLY LINE OF SAID ROAD THENCE CONTINUE ALONG THE LAST DESCRIBED COURSE 178 FEET FOR THE POINT OF BEGINNING THENCE

Leaking Underground Storage Environmental Tank Notice

1101849087 Page: 2 of 10

UNOFFICIAL COPY

Subsequent discovery of contaminants, not identified as part of the investigative or remodial activities upon which the issuance of the leader was based, that pose a threat to human health or the custiconnects.

Suppose an accurate and official copy of this Letter, as recorded to

Hilpox Environmental Protection Agency isuscept of Land - #24 Loakin Onderground Storage Tank Section 4011 No. 4 Grand Avenue East Post Office Bar 19276 Springfield, IL 69794-9276

If you have any questions or need further assistance, please contact the fillinois EPA project or St. тыпыды. Sieve Jones, at 217/524-1253 or Steve Jones@illinois.gov.

Sincely

Thurs A Hountager

Main Manager

Leaking Underground Storage Tank Section

Division of Remediation Management

Bucanofland

NAS SECTION (Exec Airport 20071356 CACR Dec 2010.000

Attachments: Ceaking Underground Storage Tank Environmental Notice Site Base Map

withage of Wheeling, attn: Dennis Rouleau

HOLFILE

1101849087 Page: 3 of 10

UNOFFICIAL COPY



ILLINOIS ENVIRONMENTAL PROTECTION AGENCY

1021 North Grand Avenue East, P.O. Box 19276, Springfield, Illinois 62794-9276 ◆ (217) 782-2829 James R. Thompson Center, 100 West Randolph, Suite 11-300, Chicago, IL 60601 ◆ (312) 814-6026

PAT QUINN, GOVERNOR

DOUGLAS P. SCOTT, DIRECTOR

217/782-6762

CERTIFIED MAIL

JAN 1 2 2011

7009 2820 0001 7489 6089

Mr. Mark Costa Signature Flight Support 1100 South Milwaukee Avenue Wheeling, Llir ois 60009

Re:

LPC #6314977699 -- Cook County

Wheeling/Cricago Executive Airport (Signature Flight Support Jet-A USTs)

1126 South Milwankee Ave.

Leaking UST Incident No. 20071356

Leaking UST Technical File

Dear Mr. Costa:

The Illinois Environmental Protection Agency (Illinois EPA) has reviewed the Corrective Action Completion Report submitted for the above-referenced incident. This information was dated December 6, 2010 and was received by the Illinois EPA on December 8, 2010. Citations in this letter are from the Environmental Protection Act (Act), as amended by Public Act 92-0554 on June 24, 2002, and Public Act 96-0908 on June 8, 2010, and 35 Illinois Administrative Code (35 Ill. Adm. Code).

The Corrective Action Completion Report and associated License a Professional Engineer Certification submitted pursuant to Section 57.7(b)(5) of the Act and 35 Ill. Adm. Code 734.135(d) indicate corrective action for the above-referenced site was conducted in accordance with the Corrective Action Plan approved by the Illinois EPA. The Corrective Action Completion Report demonstrates that the requirements of Section 57.7(b) of the Act have been satisfied.

Based upon the certification by William Butler, a Licensed Professional Engineer, and pursuant to Section 57.10 of the Act (415 ILCS 5/57.10), your request for a no further remediation determination is granted under the conditions and terms specified in this letter.

Issuance of this No Further Remediation Letter (Letter), based on the certification of the Licensed Professional Engineer, signifies that: (1) all statutory and regulatory corrective action requirements applicable to the occurrence have been complied with; (2) all corrective action concerning the remediation of the occurrence has been completed; and (3) no further corrective action concerning the occurrence is necessary for the protection of human health, safety, and the environment. Pursuant to Section 57.10(d) of the Act, this Letter shall apply in favor of the following parties:

1101849087 Page: 4 of 10

UNOFFICIAL COPY

17-17-5

- Signature Flight Support, the owner or operator of the spacehold storing stank searches).
- See parent corporation or subsidiary of such owner or operator
- Any co-owner or co-operator, either by joint tenance regim-of-survivorship, or any other gar a haring a legal relationship with the owner or operator to whom the factor is issued.
- A stay hold mot a beneficial interest of a land mist, or after vivos must whether revocable or impropalate.
- hav mortgagee or grastee of a deed of trust of such owner or operator,
- 6 Any successor-in-interest of such owner or operator
- Any transferce of such owner of operator whether the transfer was by said, bankruptcy producteding, partition, dissolution of marriage, settlement of adjustication of any civil action, charitable gift, or bequest.
- 8. Any hear or devisee of such owner or operator
- An owner of a parcel of real property to the extent that this Letter applies to the observence on that parcel.

Letter and all attachments, including but not limited to the Leaking Colorground Storage Tank environmental Notice, must be filled within 45 days of receipt as a single instrument with the Office of the Recorder or Registrar of Titles in the county in which the above-referenced site is located. This Letter shall not be effective until officially recorded by the Office of the Recorder or Registrar of Titles of the applicable county in accordance with Illinois iaw so a forms a permanent part of the chain of title for the above-referenced property. Within 30 days of this Letter being recorded, an accurate and official copy of this Letter, as recorded, shall be obtained and submitted to the Illinois EPA. For recording purposes, it is recommended that the Leaking chairground Storage Tank Environmental Notice of this Letter by the first page of the Instrument filed.

CONDITIONS AND TERMS OF APPROVAL

LEVEL OF REMEDIATION AND LAND USE LIMITATIONS

The remediation objectives for the above-referenced site, more particularly described in the Leaking Underground Storage Tank Environmental Notice of this Letter, were astablished in accordance with the requirements of the Turced Approach to Corrective Autom Objectives (35 III. Adm. Code 742) rules

1101849087 Page: 5 of 10

UNOFFICIAL COPY

Page 3

- 2. As a result of the release from the underground storage tank system(s) associated with the above-referenced incident, the above-referenced site, more particularly described in the attached Leaking Underground Storage Tank Environmental Notice of this Letter, shall not be used in a manner inconsistent with the following land use limitation: There are no land use limitations. The groundwater under the site as shown on the attached Site Base Map shall not be used as a potable water supply.
- 3. The land use limitation specified in this Letter may be revised if:
 - a. Further investigation or remedial action has been conducted that documents the attainment of objectives appropriate for the new land use; and
 - A new No Further Remediation Letter is obtained and recorded in accordance b. with Title XVII of the Act and regulations adopted thereunder.

PREVENTIVE, ENGINEERING, AND INSTITUTIONAL CONTROLS

4. Preventive: The groundwater under the site described in the attached Leaking Underground Storage Tank Environmental Notice of this Letter and shown on the attached Site Base Mar, shall not be used as a potable supply of water. No person shall construct, install, maintain, or utilize a potable water supply well. In accordance with Section 3.65 of the Act, "potable" means generally fit for human consumption in accordance with accepted water supply principles and practices.

Prior to commencement of any future excavation and/or construction in or near the contaminated zone of the remediation site, a safety plan for this remediation site is required that is consistent with the National Institute for Occupational Safety and Health Guidance Manual for Hazar Jous Waste Site Activities; Occupational Safety and Health Administration regulations, particularly in 29 CFR 1910 and 1926; state and local regulations; and other U.S. EPA guidance as provided. At a minimum, the plan should address possible worker exposure if any future excavation and construction activities occur within the contaminated soil.

Engineering: None.

Institutional: This Letter shall be recorded as a permanent part of the chain of title for the above-referenced site, more particularly described in the attached Leaking Underground Storage Tank Environmental Notice of this Letter.

1101849087 Page: 6 of 10

UNOFFICIAL COPY

17.815

haffure to establish operate, and maintain controls in full compliance with he Acq applicable regulations, and the approved corrective action plant if applicable, may result in voidance of this Letter.

OTERS TERMS

- The Approximation of the solutions and regulations and regulations and the solution of the solution of the solution of the solution of this Letter, must be handled in accordance with all applicable lasts and regulations under 35 Hz. Adm. Code Submits G.
- Further information regarding the above-referenced site can be obtained through a written request under the Freedom of Information Act (5 IUCS 140) to

Hunois Environmental Protection Agency
Attention: Freedom of Information Act Office:
Bureau of Land - #24
1021 North Grand Avenue Eas:
Post Office Box 19276
Springfield, IL 62794-9276

- Enriquent to 35 III. Adm. Code 734.720, should the fillipois EPA seek to void this Letter, the Illinois EPA shall provide Notice of Voidance to the experies operator of the leaking underground storage tank system(s) associated with the above exterenced meident and the current title holder of the real estate on which the tanks were located, at their last known addresses. The notice shall specify the cause for the voidance, explain the provisions for appeal, and describe the facts in support of the voidance. Specific acts or araissions that the result in the voidance of this Letter include, but shall not be limited to
 - Any violation of institutional controls or industrial/commercial land use restrictions;
 - Line failure to operate and maintain preventive or argineering controls or to comply with any applicable groundwater monitoring plan
 - The disturbance or removal of contamination that has been left in place in accordance with the Corrective Action Plan or Completion Report.
 - The failure to comply with the recording requirements for the Letter
 - Obsuming the Letter by fraud or misrepresentation, or

UNOFFICIAL COPY

Page 2

SOUTHEASTERLY AT A RIGHT ANGLE 131.50 FEET THENCE SOUTH 64° 29' 00" WEST 76.50 THENCE NORTHWESTERLY AT A RIGHT ANGLE 131.50 FEET THENCE NORTH 64° 29′ 00″ EAST 76.50 FEET TO THE POINT OF BEGINNING, AND EXCEPT THAT PART COMMENCING AT THE INTERSECTION OF THE NORTH LINE OF LOT 2 EXTENDED AND THE CENTER LINE OF MILWAUKEE AVENUE THENCE SOUTHEASTERLY ALONG SAID CENTERLINE 48.50 FEET THENCE SOUTH 64° 29' WEST TO THE SOUTHWESTERLY LINE OF SAID ROAD THENCE SOUTHEASTERLY ALONG SAID SOUTHWESTERLY LINE 26 FEET FOR THE POINT OF BEGINNING THENCE SOUTH 64° 29' WEST 155 FEET THENCE SOUTHEASTERLY AT RIGHT ANGLE 29 FEET THENCE SOUTH 64° 29' WEST 56 FEET THENCE SOUTHEASTERLY AT RIGHT ANGLE 34.50 FEET THENCE NORTH 64° 29' EAST 57 FEET THENCE SOUTHEASTERLY AT RIGHT ANGLE 49 FEET THENCE NORTH 64° 29' EAST 155 FEET TO THE SOUTHWESTERLY I INE OF SAID ROAD THENCE NORTHWESTERLY ALONG SAID SOUTHWESTERLY LINE TO THE POINT OF BEGINNING AND EXCEPT THAT PART COMMENCING AT THE INTERSECTION OF THE NORTH LINE OF LOT 2 EXTENDED EAST AND THE CENTERLINE OF MILWAUKEE AVENUE THENCE SOUTHEASTERLY ALONG SAID CENTERLINE 48.50 FEET THENCE SOUTH 64° 29' WEST TO THE SOUTHWESTERLY LINE OF SAID ROAD THENCE CONTINUING ALONG THE LAST DESCRIBED LINE 178 FEET THENCE SOUTHEASTERLY AT RIGHT ANGLE 176.50 FEET FOR A POINT OF BEGINNING THENCE CONTINUING ALONG THE LAST DESCRIBED LINE 97 FEET THENCE NORTH 64° 29' EAST 90 FEET THENCE NORTHWESTERLY AT RIGHT ANGLE 97 FEET THENCE SOUTH 64° 29' WEST 90 FEET TO THE POINT OF BEGINNING AND EXCEPT THAT PART COMMENCING AT THE INTERSECTION OF THE NORTH LINE OF LOT 2 EXTENLED EAST AND THE CENTERLINE OF MILWAUKEE AVENUE THENCE SOUTHEASTERLY ALONG SAID CENTERLINE 48.50 FEET THENCE SOUTH 64° 29' TO THE SOUTHWESTERLY LINE OF SAID ROAD THENCE CONTINUING ALONG THE LAST DESCRIBED LINE 211 FEET THENCE SOUTHEASTERLY AT KIGHT ANGLE 55 FEET TO THE POINT OF BEGINNING THENCE CONTINUIN & ALONG THE LAST DESCRIBED LINE 34.50 FEET THENCE NORTH 64° 29' EAST THENCE SOUTHEASTERLY AT RIGHT ANGLE THENCE SOUTH 64° 29' WEST 139 FEET THENCE NORTHWESTERLY AT RIGHT ANGLE 104.50 FEET THENCE NORTH 64° 29' EAST 123 FEET TO THE POINT OF BEGINNING AND EXCEPT THAT PART BEGINNING AT A POINT ON THE NORTH LINE OF PALATINE ROAD 120 FEET WEST OF THE INTERSECTION WITH THE WESTERLY LINE OF MILWAUKEE AVENUE THENCE NORTH 99 FEET THENCE WEST 184.50 FEET THENCE SOUTH 24.50 FEET THENCE WEST 80.50 FEET THENCE SOUTH 24.50 FEET TO THE NORTH LINE OF PALATINE ROAD THENCE EAST ALONG SAID

1101849087 Page: 8 of 10

UNOFFICIAL COPY

Promise

LINE 204.50 FEET TO THE POINT OF BEGINNING AND EXCEPT THAT PART OF LOTE A DESCRIBED AS FOLLOWS: BEGINNING AT A POINT 600 FEET BAST AND IS SEET NORTH OF THE SOUTHWEST CORNER OF LOTE THENCE EAST 269.05 FEET NORTH 161 FEET WEST 269.05 FEET THENCE SOUTH 161 FEET TO THE POINT OF BEGINNING.

Common Address: 1126 South Milwaukee Avenue, Wirechns, Illinois

Key Estate Tax Index/Parcel Index Number: (B-15-400-03)

Sile Owner: Village of Wheeling and the City of irrespect Heights

I and I so i imitation: There are no land use limitations. The groundwater under the site as shown of the attached Site Base Map shall not be used as a potable water supply.

See the attached be Further Remediation Letter for other terms.


SIChi Face Airport 20071 Sto CACR Dec 2010 doc

Leaking Underground Storage Environmental Lank Notice

1101849087 Page: 9 of 10

UNOFFICIAL COPY

Site Base Map
LPC #0314977699 -- Cook County
Chicago Executive Airport (Signature Flight Support)
Leaking UST Incident No. 20071356
Area Addressed by Groundwater Use Restriction



SJ\Chi Exec Airport 20071356 CACR Dec 2010.doc

1101849087 Page: 10 of 10

UNOFFICIAL COPY



DINOB INVESTMENTS PRINTED BY ALIEN

the same of many of ARR has

RECORDING REQUIREMENTS FOR NO FURTHER REMEDIATION LETTERS

Miroductus

The Hurst Environmental Protection Agency's (Illinois LPA) Bureau of Landaueaking inderground Storage Tank Section issues a No Further Remodiation (NFR) Letter after a demonstration of compliance with Title XVI of the Environmental Protection Act and applicable equivations is made. The NFR Letter signifies that: (1) all statutory and regulatory corrective action requirements approable to the occurrence have been complied with, (2) all corrective action concerning the conediation of the occurrence has been complied, and (3) no further corrective action concerning to occurrence is necessary so long as the title is used in accordance with the terms and conditions of the NFR Letter.

Significance

When properly recorded, the NFR Letter solds legal significance for all applicable parties confined at Section 57-10(d) of the Environmental Protection Acr. (See 415 ILCS 5/57.10(d).) If not properly recorded, the Illinois EPA will take seens to veid the NFR Letter in secondance with the regulations.

Duty to Record

The duty to record the NFR Letter is mandatory. You must submit the NFR Letter, with a copy of any applicable institutional controls proposed as part of a corrective action completion report, to the Office of the Recorder or the Registra. of Titles of the county in which the site is located within 45 days after receipt of the NFR Letter. You must record the NFR Letter and any attachments. The NFR Letter shall be filed in accordance with Illinois law so that at forms a permanent part of the chain of title to ensure current and future users of the property will be informed of the conditions and terms of approval including level of remediation; land use limitations; and preventive, engineering, and institutional controls. A certified or otherwise accurate and official copy of the NFR Letter and any attachments, as recorded, must be submitted to the Illinois EPA. Vailure to record the NFR Letter in accordance with the regulations will make the NFR Letter voidable.

For Nove Information

Phrase refer to Tiered Approach to Corrective Action Objectives (TAGO) Fact Sheet 3 is allable from the Himois EPA by calling 1-888-299-9533 or by accessing it on the Illinois EPA. Web site to http://www.upa.state.il.us/land/taco/3-no-further remediation-ferters.html.

Projection of the Company of the Com