



PARCEL 1:

146 IN THE WALDEN CONDOMINIUM, AS AS DELINEATED INTT NO. ON A SURVEY OF

PART OF FRACTIONAL SECTION 1 TOGETHER WITH PART OF THE NORTH 1/2 OF THE NORTH 1/2 OF SECTION 12, BOTH IN TOWNSHIP 11 NORTH, RANGE 10 EAST OF THE THIRD PRINCIPAL M.FIDIAN IN COOK COUNTY, ILLINOIS,

WHICH SURVEY IS ATTACHE) AS EXHIBIT 'A' TO THE DECLARATION OF CONDOMINIUM RECORDED AS DOCUMENT 24764365 TOGETHER WITH ITS UNDIVIDED PERCENTAGE INTE EST IN THE COMMON ELEMENTS.

PARCEL 2:

THE EXCLUSIVE RIGHT TO THE USE OF MARKING SPACE BECOMEN ELEMENT, AS DELINEATED ON TAY SURVEY ATTACHED TO AFORESAID RECORDED AS DOCUMEN': '4764865. A LIMITED TO THE DECLARA

.PARCEL 3:

EASEMENT FOR INGRESS AND EGRESS FOR THE B'NEFIT OF PARCELS 1 AND 2, AS SET FORTH IN THE GRANT RECORDED AS DOCUMENT 21218271, THE DECLARATION RECORDED AS DOCUMENT 21218277, AS MODIFIED BY DOCUMENT 21314070, AND AS CONFIRMED BY GRANT RECORDED AS DOCUMENT 21314484, AS AMENDED BY DOCUMENT 2132/390.

GRANTOR ALSO HEREBY GRANTS TO GRANTEE, THEIR SUCCISSORS AND ASSIGNS, AS RIGHTS AND EASEMENTS APPURTENANT TO THE LLOVE DESCRIBED REAL ESTATE, THE RIGHTS AND EASEMENTS FOR THE BENEFIT OF SAID PROPERTY SET FORTH IN THE DECLARATION OF CO. DC. ATMIUM, AFORESAID, AND GRANTOR RESERVES TO ITSELF, ITS SUCCESS, K. AND ASSIGNS, THE RIGHTS AND EASEMENTS SET FORTH IN SAID DECLARATION FOR THE BENEFIT OF THE REMAINING PROPERTY DESCRIBED THEPSIN.

THIS CONVEYANCE IS SUBJECT TO ALL RIGHTS, EASEMENTS, RESTRICTIONS, CONDITIONS, COVENANTS AND RESERVATIONS CONTAINED IN SAID DECLARATION THE SAME AS THOUGH THE PROVISIONS OF SAID DECLARATION WERE RECITED AND STIPULATED AT LENGTH HERE.

## ехитвіт В

## RENOVATION AND REFURBISHING WORK

- 1. Tuckpoint and caulk as necessary.
- 2. Roof repair; as necessary.
- 3. Repair parapet flashing.
- 4. Clean and paint exposed steel members around perimeter of halonies with a rust preventative paint.
- 5. Replace wood balcomy railings as necessary.
- 6. Paint exposed wool or balconies as required.
- 7. Exterior painting as necessary.
- 8. General upgrading of landscaping.
- 9. General upgrading of common areas.
- 10. Paint laundry rooms.
- 11. Improve ventilation in laun(ry room.
- Replace boiler breeching insulation in both boiler rooms.
- 13. Clean and paint breeching as required.
- 14. Replace boiler control panel in Building 1912
- Install mechanical ventilation in ga bage/compactor room.
- 16. Replace missing fire extinguishers.
- 17. Improve fire protection system as required.
- 18. Miscellaneous electrical repairs as necessary
- 19. Install water softeners in both buildings.